MATERIAL SAFETY DATA SHEET

Manufacturer's Name

RACINE INDUSTRIES, INC.

Address:

1405-16th ST., RACINE, WI 53403

Telephone:

1-414-637-4491

Product Information

Brand Name:

HOST Spot Remover For Carpets

Product Type:

Mixture of water, detergent, solvents.

Usages:

Dissolving spots in residential and commercial carpets. Applied sparingly to cotton towel and then

to carpet spot.

Toxicity Test Data*

Primary Skin Irritant:	(Yes _)	(No	X)
Oral Toxicity:	(Yes		(No	X)
Inhalation Toxicity:	(Yes		(No		
Eye Irritant:	(Yes	_)	(No	X)

* In accordance with Consumer Product Safety Commission and Federal Hazardous Substances Act regulations.

Hazardous Ingredients:	CAS No.	% Wt.	TLV
Mineral Spirits, Aliphatic 1,1,1, Trichloroethane	64742-48-9	19.0	300 ppm
	71-55-6	25.0	350 ppm

Physical Data

Boiling Point (F) Liquid Portion : 170 Vapor Pressure (mm Hg) @ 21C 17.74 Vapor Density (Air = 1) N/A Solubility in Water : 100% Specific Gravity (Water = 1) .99 Percent Volatile by Volume (%) : 100 Evaporation Rate (Ether **-1**) : <1 Concentrate: N/A In Use : 7.75

Appearance and Odor : White liquid. Mild/sweet

odor.

Fire and Explosion Hazard Data

Flash Point (COC Method) : 172F Flammable Limits : N/A

Extinguishing Media : Self-contained. Will not sus-

tain a flame.

Special Fire Fighting Procedures : None Unusual Fire and Explosion Hazards: None

Health Hazard Data

Threshold Limit Value : N/A

Primary Route(s) of Entry: Skin, inhalation.

Symptoms of Overexposure or Extreme Sensitivity: No known harmful effects from repeated, long-term exposure. Persons with detergent or hydrocarbon sensitivity could experience mild skin rash from prolonged direct contact with product. Purposeful inhalation of vapors may produce dizziness.

Emergency and First-Aid Procedures Overexposure: Fresh air. Wash hands with water. Flush eyes. Extreme Sensitivity: Fresh Air. Wash hands with water. Flush eyes. Seek advice of physician. Toxic (NTP): (Yes) (No X) Carcinogenic: IRAC (Yes ___) (No _X) OSHA (Yes __) (No X) Reactivity Data Stability: (Stable X) (Unstable _) Conditions to Avoid: None known. Incompatability (Materials to Avoid): None known. Hazardous Decomposition Products: Water vapor; CO2,; Acid gasses; alcohol; hydrogen chloride. Hazardous Polymerization Occurs: (Yes ___) (No <u>X</u>) Conditions to Avoid: None known. Spill or Leak Procedures If Spilled: Mop, wipe or soak up with absorbent material, cotton or paper toweling. Flush area with water and mop dry. Waste Disposal: Can be landfilled. Special Protection Requirements Respiratory: (Yes ___) (No X) Ventilation: (Yes ____) (No X) Gloves: (Yes ___) (No \overline{X}) Eye Protection: (Yes

Suggested Precautions

Other:

Handling: Treat like any cleaning product. Storing: Treat like any cleaning product. Use:

___ >

(Yes ___) (No X)

(No X)

Provide good general ventilation. For sensitive skin, use plastic gloves. Do not ingest. Avoide direct contact to eyes. Product is safe, but it is a cleaner.

Data Sheet Prepared by Name : G. B. Rench Address : 1405-16th ST. City, State: Racine, WI 53403 Telephone : 414-637-4491	In Emergency, Contact 1. Q. H. Rench
	1-800-558-9439 2. N. K. Harris 414-637-4491

Racine Industries, Inc. (RI) furnishes the data contained herein in good faith at customer's request without liability or legal responsibility for same whatsoever and no warranty or guarantee, express or implied, is made with respect to such data nor does RI grant permission, recommendation or inducement to infringe any patent whether owned by RI or others. The data is offered solely for your information and consideration. Since conditions of use are beyond RI's control, user assumes all responsibility and risk.