MATERIAL SAFETY DATA SHEET

SECTION I

: VOLU-SOL (LOGOS SCIENTIFIC, INC.) EMERGENCY MANUFACTURER'S NAME : 700 SUNSET ROAD, HENDERSON, NV 89015 PHONE NO.: ADDRESS 702/565-1383 CHEMICAL NAME/SYNONYMS: STAT STAIN

QUICK WRIGHT GIEMSA STAIN TRADE NAME/SYNONYMS :

FORMULA: CH30H+STAIN ALCOHOL CHEMICAL FAMILY

SECTION II - HAZARDOUS INGREDIENTS PAINTS, PRESERV. & SOLVENTS! % ITLV/UNITS ALLGYS & METALLIC COATINGS!% ITLV/UNIT PIGMENTS: WRIGHT&GIEMSA 14.51

191 1 SOLVENTS: METHANOL. ADDITIVES: SALTS & 1 INTENSIFIERS 14-21

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES 1 % ITLY (UNITS)

SECTION III - PHYSICAL DATA

|SPECIFIC GRAVITY(H20=1): 0.7931 BOILING POINT(DEG.F: 149

1% VOLATILE BY VOL.(%) : 96 91 VAPOR PRESSURE (MMHG:

1.11 | EVAPORATION RATE VAPOR DENSITY(AIR=1:

: 1 SOLUBILITY IN WATER: COMPLETE (ETHER____=1)

APPEARANCE AND ODOR: BLUE LIQUID

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT/METHOD USED: 52F (TCC) 61F (TOC)

UEL: 36 FLAMMABLE LIMITS: LEL: 6.7

: DRY CHEMICAL, CARBON DIOXIDE, "ALCOHOL" FOAM EXTINGUISHING MEDIA

SPECIAL FIRE FIGHTING PROCEDURES : NONE

UNUSUAL FIRE AND EXPLOSION HAZARDS: BURNS WITH AN INVISIBLE FLAME IN DAYLIGHT.

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE : 200 PPM (SKIN)

EFFECTS OF OVEREXPOSURE: HARMFUL IF INHALED, MAY BE FATAL OR CAUSE BLINDNESS

IF SWALLOWED, WILL IRRITATE THE SKIN OR EYES.

EMERGENCY AND FIRST AID PROCEDURES

INGESTION : INDUCE VOMITING. CALL A PHYSICIAN.

INHALATION: MOVE TO FRESH AIR. GIVE ARTIFICIAL RESPIRATION IF NOT BREATHING.

EYE CONTACT: FLUSH WITH WATER FOR 15 MIN., CALL A PHYSICIAN.

SKIN CONTACT: FLUSH WITH WATER.

SECTION VI - REACTIVITY DATA

STABLE STABILITY:

INCOMPATABILITY/MATERIALS TO AVOID: REACTS VIGOROUSLY WITH STRONG OXIDIZERS. CHROMIC ANHYDRIDE, LEAD PERCHLORATE, PERCHLORIC ACIDS.

HAZARDOUS DECOMPOSITION PRODUCTS : OCCURS FROM HEAT & REACTION WITH MATERIALS

ABOVE.

: WILL NOT OCCUR. HAZARDOUS POLYMERIZATION

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

ABSORB SPILLS ON PAPER AND DISPOSE OF PAPER. FLUSH AREA WITH WATER

(USE METHANOL TO REMOVE STAIN.)

WASTE DISPOSAL METHOD

FLUSH TO CHEMICAL SEWER OR INCINERATE. COMPLY WITH CURRENT LOCAL, STATE AND FEDERAL REGULATIONS.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION/SPECIFY TYPE: NONE FOR NORMAL USE

VENTILATION: LOCAL EXHAUST : USE IN WELL VENTILATED AREA

MECHANICAL/GENERAL :

PROTECTIVE GLOVES : NONE

EYE PROTECTION : SAFETY GLOGGLES

OTHER PROTECTIVE EQUIPMENT : LAB COAT

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING:

USE ONLY IN WELL VENTILATED AREA, BOTTLE SHOULD REMAIN CAPPED AND SEALED UNTIL USE. AVOID STORAGE IN AREAS OF EXTREME TEMPERATURE AND DIRECT LIGHT.

AVOID CONTACT WITH EYES.

OTHER PRECAUTIONS

KEEP AWAY FROM HEAT SPARKS AND FLAME, STORE IN VENTILATED AREA.

LAST PAGE