

SANFORD CORPORATION
2740 WASHINGTON BLVD.
BELLWOOD, IL. 60104

Sanford Corporation has been advised by counsel that the OSHA Hazard Communication Standard does not apply to the Sanford product described in this MSDS. The reason for this exemption is contained in 29 CFR Part 1910.1200 (b) (6) (vii) as amended August 24, 1987 per Federal Register Vol. 52, No. 161, p 31877-31878. The information contained in this MSDS is forwarded to you for your information but is not meant to imply that the product is covered by the Hazard Communication Standard nor is the MSDS meant to comply with all requirements of the Hazard Communication Standard.

EMERGENCY TEL: 1-800-228-5635

DATE OF LAST REVISION:

January 14, 1988

DOCUMENT SEQUENCE NO.:

170-43

MAY 18 1994

1. IDENTIFICATION:

NAME: Roll-On Stamp Pad Inker
COLORS: Black, Red, Green, Brown

2. COMPOSITION:

Dye

Solvents: water
glycerine (56-81-5)
diethylene glycol (111-46-6)
polyethylene glycol (25322-68-3)

3. PHYSICAL DATA:

(for glycerine)

BOILING POINT: greater than 550°F at 760 mm Hg
SPECIFIC GRAVITY: 1.2 - 1.3 at 22°C
VAPOR PRESSURE: less than 0.1 mm Hg at 72°F
VAPOR DENSITY: not available
EVAPORATION RATE: not available
SOLUBILITY IN WATER: complete
APPEARANCE/ODOR: water white, clear liquid, bland odor
FLASH POINT: greater than 390°F (PMCC)
LOWER FLAMMABILITY LIMIT: not available
UPPER FLAMMABILITY LIMIT: not available

170-43

4. REACTIVITY:

STABILITY: stable

POLYMERIZATION: will not occur

CONDITIONS TO AVOID: not available

INCOMPATIBLE MATERIALS: not available

HAZARDOUS DECOMPOSITION PRODUCTS: not available

5. HEALTH HAZARD DATA:

This product is not considered toxic under Federal Hazardous Substances Act regulations, Title 16, Part 1500.

Neither the product nor any of the ingredients has been found to be a carcinogen or potential carcinogen by NTP, IARC, or OSHA.

The product is considered safe when used under normal use conditions.

6. SAFE HANDLING AND USE PRECAUTIONS:

HANDLING AND STORAGE: Do not squeeze bottle. Keep cap on bottle when not in use.

CLEAN UP PROCEDURES: Wipe up with absorbent material and discard as solid waste.

WASTE DISPOSAL MEANS: Discard as solid waste.

7. PERSONAL PROTECTION AND EXPOSURE CONTROL MEASURES:

EYE PROTECTION: None under normal use conditions.

SKIN PROTECTION: None under normal use conditions.

RESPIRATORY PROTECTION: None under normal use conditions.

VENTILATION: None under normal use conditions.