

JUL 22 1992

7912-7911
Page #1

RICOH CORPORATION
MATERIAL SAFETY DATA SHEET

01/22/92

Section I. General Information

MSDS Identifier Code
Supplier ID: Ricoh Product Code: 4120-36

Identity: Toner Pak - Black (Savin)

Manufacturer's Name and Address:
Ricoh Corporation
5 Dedrick Place
West Caldwell, NJ 07006

Distributor's Name and Address:
Savin Corporation
P.O. Box 10270
Stamford, CT 06904

Emergency Telephone Number: (800) 336-6737

Telephone Number for Information: (201) 882-2000, (800) 336-6737

Synonyms & Common Names: Savin Product Code - 7912, Toner Pak - Black (Savin),
Savin T-D Pak-7911

Uses: 7230/7300/7350/7450

Hazard Classes: Combustible Liquid N.O.S.

Chemical Formula: Mixture

Registry numbers
CAS Number: 0-00-0
RTECS Number: N/App

Date Prepared: 11/05/91 Filed/Prepared By: Kristina Sage

Section II. Hazardous Ingredients/Identity Information

Composition

Component	%	CAS #	OSHA Pel	ACGIH TLV
Hydrotreated Heavy Naphtha	89.00	64742-48-9	N/App	300ppm**
*Carbon Black	02.00	1333-86-4	3.5mg/m3	3.5mg/m3
Acrylic Polymer	03.00	25068-63-7	N/App	N/App
*Wax	06.00	9002-88-4	N/App	N/App

*Carbon Black is listed on the Massachusetts
Substance List and the IARC Monograph.

*Wax is listed on the IARC Monograph.

The IARC has evaluated the evidence for the
carcinogenicity of Carbon Black and Wax as
inadequate to determine a carcinogenic risk
for humans.

**Recommended by Exxon

JUL 22 1994

7912-7911
Page #2

RICOH CORPORATION
MATERIAL SAFETY DATA SHEET

01/22/92

Exposure Limits (TLV/PEL)
OSHA: See data above
NIOSH: Not applicable
ACGIH: See data above
State: Not applicable
Other: None

Section III. Physical/Chemical Characteristics

Boiling Point: 161-199C Specific Gravity: 0.78@15.6C
Vapor Pressure: <10mmHg @ 25C % Volatile by Volume: Not applicable
Melting Point: Not applicable Vapor Density (Air=1): Greater than 5
Evaporation Rate (n-BuAc=1): Approx. 0.3

Solubility in Water: Negligible: Less than 0.1%

Appearance and Odor: Black liquid, faint petroleum hydrocarbon odor.

Section IV. Fire and Explosion Hazard Data

Flash Point and Method: 41C T.C.C.

Explosive Limits: LEL 0.7 UEL 6.5
Comments: Not applicable

Extinguishing Media: Foam, dry chemicals, or carbon monoxide.

Special Fire-Fighting Procedures: If a leak or spill has ignited, use standard fire-fighting procedures for petroleum based liquids. Minimize breathing gases, vapor, fumes or decomposition products. Fire-fighters should use supplied-air breathing equipment for enclosed or confined spaces or as otherwise needed.

Unusual Fire and Explosion Hazards: Not applicable

Section V. Reactivity Data

Stability: Stable
Conditions to Avoid: Not applicable

Incompatibility (Materials to Avoid): Avoid contact with strong oxidizers such as liquid Cl₂ or conc. O₂.

Hazardous Decomposition or Byproducts: Will not occur.

Hazardous Polymerization: Will not Occur
Conditions to Avoid: Not applicable

Section VI. Health and Hazard Data

Routes of Entry: Skin, inhalation, ingestion

Health Hazards of Short-Term exposure (Acute)

Eyes: Slight conjunctival irritation.

Skin: Mild irritation under conditions of excessive exposure.

Inhalation: No untoward effects.

LD50 (rat): Greater than 12,400 mg/m³ (Approximately 2000 ppm)

Ingestion: Acute oral toxicity: Greater than 5g/kg bodyweight.

Health Hazards of Long-Term exposure (Chronic): Health studies have shown that many petroleum hydrocarbons and synthetic lubricants pose potential human health risks which may vary from person to person. As a precaution, exposure to liquid, vapor, mist or fumes should be minimized.

Carcinogenicity: See Section II

NTP? No IARC Monographs? Yes OSHA Regulated? No

Signs and Symptoms of Exposure: High vapor concentrations (greater than approximately 1000 ppm) are irritative to the eyes and respiratory tract, cause headaches and dizziness, are anesthetic, and may have other central nervous system effects.

Medical Conditions Generally Aggravated by Exposure: Not applicable

Emergency and First Aid Procedures

First Aid

Eyes: If splashed into the eyes, flush with clear water for 15 minutes or until irritation subsides.

Skin: In the case of skin contact, remove any contaminated clothing and cleanse skin thoroughly with waterless hand cleaner followed by washing with soap and water.

Inhalation: If overcome by vapors, remove from exposure and call a physician immediately.

Ingestion: If ingestion occurs, do not induce vomiting; call a physician immediately.

Additional Information: Ames test result: Negative

Section VII. Precautions for Safe Handling and Use

Steps to be Taken in Case Material is Released or Spilled: Shut off and eliminate all ignition sources. Keep people away. Recover free product. Add sand, earth or other suitable absorbent to spill area. Minimize breathing vapors. Minimize skin contact. Ventilate confined spaces. Open all windows and doors. Keep product out of sewers and watercourses by diking or compounding. Advise authorities if product has entered or may enter sewers, watercourses, or extensive land areas. Assure conformity with applicable governmental regulations. Continue to observe precautions for volatile, combustible vapors from absorbed material.

Waste Disposal Method: Waste liquid should be disposed of in an environmentally safe manner and in accordance with governmental regulations. Disposal regulations vary from locality to locality, therefore, consult your local office of the EPA to determine proper method of disposal.

Precautions to Be Taken in Handling and Storing:

CAUTION - COMBUSTIBLE LIQUID

Keep away from heat, open flame and sparks. Keep out of reach of children.

Other Precautions: Empty containers retain residue (liquid and/or vapors) and can be dangerous. In order to avoid the risk of exposure, do not pressure, or expose such containers to heat, sparks or other sources of ignition.

Section VIII. Control Measures

Respiratory Protection: None needed under normal conditions of use.

Ventilation

Local Exhaust: None needed under normal conditions of use.

Special: None

Mechanical (general): Adequate ventilation

Other: None

Protective Gloves: None needed under normal conditions of use.

Eye Protection: None needed under normal conditions of use.

Other Protective Clothing or Equipment: None needed under normal conditions of use.

Work and Hygienic Practices: Minimize breathing vapor or mist. Avoid prolonged or repeated contact with skin. Remove contaminated clothing; launder or dry-clean before reuse. Remove contaminated shoes and thoroughly clean and dry before reuse. Cleanse skin thoroughly after contact, before breaks and meals,

7912 -7911
Page #5

RICOH CORPORATION
MATERIAL SAFETY DATA SHEET

01/22/92

and at the end of work periods. Product is readily removed from skin by waterless hand cleaners followed by washing with soap and water.