

=====

REACTIVITY DATA

=====

Stability: Stable

Incompatibility: Strong oxidizers

Hazardous Decomposition Products: Combustion will produce carbon dioxide and probably carbon monoxide.

Hazardous Polymerization: Will not occur.

=====

TOXICOLOGICAL PROPERTIES

=====

EXPOSURE LIMITS:

ACGIH Threshold Limit Value (TLV): Not Established

OSHA Permissible Exposure Limit (PEL): Not Established

EXPOSURE EFFECTS:

Inhalation: Dust irritating to respiratory tract.

Skin: Causes burns.

Eye: Causes burns.

TOXICITY DATA:

Test	Species	Result
Acute Oral LD50	Rat	1310 mg/kg
Skin Absorption LD50	Rabbit	GT 10 g/kg
Skin Irritation	Rabbit	Strong
Eye Irritation	Rabbit	Strong
Inhalation	Rat	GT 8.9 mg/L

Feeding Study: Rats fed diets containing the compound for 28 days consumed approximately 326 mg/kg/day.

Feed Intake: Normal

Weight Gain: Normal

No significant gross lesions were noted.

=====

PREVENTIVE MEASURES

=====

VENTILATION: Use process enclosures, local exhaust ventilation or other engineering controls to reduce dust concentrations to an acceptable level.

RESPIRATORY PROTECTION: If engineering controls are inadequate to control dust concentrations to an acceptable level, a NIOSH approved dust respirator should be worn if needed. If respirators are used, a program should be instituted to assure compliance with OSHA Standard 29CFR 1910.134.

SKIN AND EYE PROTECTION: Protective gloves and clothing should be worn. Safety glasses, goggles, or a face shield should be worn.

SPECIAL STORAGE AND HANDLING PRECAUTIONS: Keep from contact with oxidizing materials.

SPILL, LEAK, AND DISPOSAL PROCEDURES: Sweep up material and package for safe feed to an incinerator. Dispose by incineration or contract with licensed chemical waste disposal agency. Discharge, treatment, or disposal may be subject to federal, state or local laws.

=====

FIRST AID MEASURES

=====

Inhalation: Remove to fresh air. Treat symptomatically. If symptoms are present get medical attention.
Skin: Immediately flush skin with plenty of water for at least 15 minutes and get medical attention if symptoms are present after washing.
Eye: Immediately flush eyes with plenty of water for at least 15 minutes and get medical attention immediately.

=====

ADDITIONAL INFORMATION

=====

WHMIS STATUS: Controlled Product

TRANSPORTATION: For transportation information regarding this material, please phone the Eastman Kodak Distribution Center nearest you: Rochester, NY (716) 254-1300; Oak Brook, IL (312) 654-5300; Chamblee, GA (404) 455-0123; Dallas, TX (214) 241-1611; Whittier, CA (213) 945-1255; Honolulu, HI (808) 833-1661.

=====

PREPARATION INFORMATION

=====

Health and Environment Laboratories
Eastman Kodak Company
343 State Street
Rochester, NY 14650
USA

=====

The information contained herein is furnished without warranty of any kind. Users should consider these data only as a supplement to other information gathered by them and must make independent determinations of the suitability and completeness of information from all sources to assure proper use and disposal of these materials and the safety and health of employees and customers.

=====